




### Model




### Car Details

Customer/Dealer Name	Engine Capacity 1480 cc	Last Mileage 36178 km	Fuel Type Petrol
Inspection Date 24 Sep 2024	Make	Engine	VIN No
Made In USA	Registered City Washington	Transmission Type Automatic	Color Grey



## Exterior Condition



### Legend

A1:Small Scratch

U1:Small Dent

B1:Small dent with scratch (size like a thumb)

P:Paint marked

X:Need to be replaced

B2:Dent with scratch (size like at of the hand)

U2:Dent

A3:Big Scratch

A2:Scratch

S1: Rust

Y1:Small Hole or Crack

Y3:Big Hole or Crack

E1:Few Dimples

□:Minor Scratches/Dents

Body Frame Accident Checklist		95%	
Radiator Core Support	Accidented	Front Sub Frame <input type="checkbox"/>	Non-Accidented
Right Strut Tower Apron <input type="checkbox"/>	Non-Accidented		
Left Strut Tower Apron <input type="checkbox"/>	Non-Accidented		
Right Front Rail <input type="checkbox"/>	Non-Accidented		
Left Front Rail <input type="checkbox"/>	Non-Accidented		
Cowl Panel Firewall <input type="checkbox"/>	Non-Accidented		
Right A Pillar <input type="checkbox"/>	Non-Accidented		
Left A Pillar <input type="checkbox"/>	Non-Accidented		
Right B Pillar <input type="checkbox"/>	Non-Accidented		
Left B Pillar <input type="checkbox"/>	Non-Accidented		
Right C Pillar <input type="checkbox"/>	Non-Accidented		
Left C Pillar <input type="checkbox"/>	Non-Accidented		
Boot Floor <input type="checkbox"/>	Non-Accidented		
Boot Lock Pillar	Non-Accidented		
Rear Sub Frame <input type="checkbox"/>	Non-Accidented		

 Engine / Transmission / Clutch
94%

Fluids/ lters check		Exhaust check	
Engine Oil Level	Black	Exhaust Sound	Ok
Engine Oil Leakage	Leakage	Engine cooling system	
Transmission Oil Leakage	No Leakage	Radiator	Rusted
Coolant Leakage	No Leakage	Suction Fan	Working
Brake Oil Leakage	No Leakage	Transmission check / power train	
Mechanical check		Engine electronics	
Belts (AC)	Ok	Starter Operation	Ok
Belts (Fan)	Ok		
Wires (Wiring Harness)	Ok		
Engine Blow (Manual Check)	Not Present		
Engine Noise	No Noise		
Engine Vibration	No Vibration		
Cold Start	Ok		
Engine Mounts	Ok		
Pulleys (Adjuster)	Ok		
Hoses	Ok		

 Brakes
100%

Mechanical check	
Front Right Disc	Smooth
Front Left Disc	Smooth
Front Right Brake Pad	More than 50%
Front Left Brake Pad	More than 50%
Parking / Hand Brake	Ok

 Suspension/Steering
96%

Car Inspection Report -

Front suspension	
Steering Wheel Play	Ok
Right Ball Joint	Ok
Left Ball Joint	Ok
Right Z Links	Ok
Left Z Links	Ok
Right Tie Rod End	Ok
Left Tie Rod End	Ok
Front Right Boots	Ok
Front Left Boots	Ok
Front Right Bushes	Ok
Front Left Bushes	Ok
Front Right Shock	Ok
Front Left Shock	Ok

Rear suspension	
Rear Right Bushes	No Damage Found
Rear Left Bushes	No Damage Found
Rear Right Shock	Ok
Rear Left Shock	Ok

 Odometer 98%

Tempering	
Exempt from odometer disclosure	No Problem Found
Exceeds Mechanical Limits	No Problem Found
May be Altered	No Problem Found
Replaced	No Problem Found
Reading at Time of Renewal	No Problem Found
Discrepancy	No Problem Found
Call Title Division	No Problem Found
Exceeds Mechanical limits Rectified	No Problem Found

 Safety recall check

Complete safety recall	

--	--

**Stolen Vehicle Check**

No Theft record found			

**Ownership History**

1st owner			

**Ac/Heater** 100%

Ac / heater check up	
AC Fitted	Yes
AC Operational	Yes
Blower	Excellent Air Throw
Cooling	Excellent
Heating	Excellent

**Electrical & Electronics** 85%

Computer check up	
Computer Check up / Malfunction Check <input type="checkbox"/>	Error
Battery Warning Light	Not Present
Oil Pressure Low Warning Light	Not Present
Temperature Warning Light / Gauge	Not Present
Air Bag Warning Light	Not Present
Power Steering Warning Light	Not Present
ABS Warning Light	Not Present
Key Fob Battery Low Light	Not Present

Battery	
Voltage <input type="checkbox"/>	12
Terminals Condition	Ok
Charging	Ok
Alternator Operation	Ok

Instrument cluster	
Gauges	Working

**Exterior & Body** 70%

Car Inspection Report -

Car frame		Exterior lights	
Trunk Lock	Ok	Right Headlight (Working)	Working
Front Windshield Condition	Scratches	Left Headlight (Working)	Working
Rear Windshield Condition	Ok	Right Headlight (Condition)	Scratches
Front Right Door Window	Ok	Left Headlight (Condition)	Scratches
Front Left Door Window	Ok	Right Taillight (Working)	Working
Rear Right Door Window	Ok	Left Taillight (Working)	Working
Rear Left Door Window	Ok	Right Taillight (Condition)	Perfect
Windscreen Wiper	Cleaning Properly	Left Taillight (Condition)	Perfect
Sun Roof Glass	Ok	Fog Lights (Working)	Not Working

Market price analysis 15%

Classified sites price	\$6,225 below market	\$6,225 Average dealer forecourt price	\$6,225 above market
Auctions sites price	\$6,225 below market	\$6,225 Average Auction forecourt price	\$6,225 above market

Major Title Brand Check

Salvage brand	Problem reported		
Fire brand	No problem found		
Hail brand	No problem found		
Flood brand	No problem found		
Manufacturer buyback	No problem found		
Junk or Scrapped brand	No problem found		
Rebuilt or rebuildable brand	no problem found		
Export only vehicle	No problem found		

Photos

Photos

Photos

Photos

Photos

Photos

Photos

Photos

Photos

Photos



Photos

Photos

Photos

Photos

Photos

Photos

Photos

Photos

Photos

Photos

Photos

Photos

## Comments

Front bambar grill damage front L/R fender down side shield DAMAGE FRONT DOWN SIDE SHIELD NOT AVAILABLE AND DAMAGE Front side fully packed with plastic ttings and shields so some check points not visible TYER date N/A

### Disclaimer:

In case of any query or concern regarding inspection please call. This report is based on the condition of the vehicle on the date of certi cation and provides an approximate estimate of the condition on that date. Except where indicated, the parts were in working condition - this report does not take into account the condition of parts not visible or not inspected.

we has relied on the odometer reading for kms driven as seen at the time of inspection and is not responsible for verifying its genuineness. The report is in no way a commitment on the condition of the car. All reports are subjective and carexamin.com and its associates cannot be held liable in any way due to the use of this report. Unless mentioned by the dealer, cars with W1 grade paint cannot be detected by the human eye, hence it can be possible for such paint to go undetected.