

MODEL





Vehicle Details MAKE:


Last Mileage : Customer/Dealer Name Power: Fuel Type: Inspection Date : Vehicle Equipment Engine : Plate: Class: Transmission Type: Made In: Manufacture : Color: VIN: Compliance plate / RAV Registration serial number : 📋 Industry model code : entry date: safety rating:

Summary ENGINE / TRANSMISSION / CLUTCH **BRAKES** 86% 87% SUSPENSION/STEERING 84% 82% INTERIOR AC/HEATER 82% **ELECTRICAL & ELECTRONICS** 88% 85% 88% **EXTERIOR & BODY TYRES** Overall Rating: 9.3/10

www.carexamin.com 1/6



Exterior Condition



Grade: 4

Legend

A1:Small Scratch

U1:Small Dent

B1:Small dent with scratch (size like a

thumb)

P:Paint

X:Need to be replaced

B2:Dent with scratch (size like at of the

hand)

U2:Accidents

A3:Big Scratch

A2:Scratch

S1: Rust

Y1:Small Hole or

Crack

Y3:Big Hole or Crack

E1:Few Dimples

□:Minor Scratches/Dents

Body Frame Accident Checklist	
Radiator Core Support	Non-Accidented
Right Strut Tower Apron	Non-Accidented
Left Strut Tower Apron	Non-Accidented
Right Front	Non-Accidented
Left Front	Non Accidented
Cowl Panel Firewall	Non-Accidented
Right A Pillar	Non-Accidented
Left A Pillar	Non-Accidented
Right B Pillar	Non-Accidented
Left B Pillar	Non-Accidented
Right C Pillar	Non-Accidented
Left C Pillar	Non-Accidented
Boot Floor	Non-Accidented
Boot Lock Rear End	Non-Accidented

Front Sub Frame Non-Accidented

www.carexamin.com 2/6



Clutch	
Fluids/ lters check	
Engine Oil Level	Brown
Engine Oil Leakage	No Leakage
Transmission Oil Leakage	No Leakage
Coolant Leakage	Minor Leakage
Brake Oil Leakage	No Leakage

Exhaust check	Ok
Exhaust Sound	Ok
Engine cooling system	Ok
Radiator	Good Condition
Suction Fan 🛘	Working

Mechanical check	
Belts (AC)	Ok
Belts (Fan)	Ok
Wires (Wiring Harness)	Ok
Engine Blow (Manual Check)]	Ok
Engine Noise	No Noise
Engine Vibration	No Vibration
Cold Start	Ok
Engine Mounts	Ok
Pulleys (Adjuster)	Ok
Hoses	Ok

Engine electronics	Ok
Starter Operation	Working

Transmission check / power train

Brakes

Mechanical check	
Front Right Disc	Smooth
Front Left Disc	Smooth
Front Right Brake Pad	More than 75%
Front Left Brake Pad	More than 70%
Parking / Hand Brake	Good



Suspension/Steering

www.carexamin.com 3/6



Front suspension	
Steering Wheel	Ok
Play	Ok
Right Ball Joint	Ok
Left Ball Joint	Ok
Right Z Links	Ok
Left Z Links	Ok
Right Tie Rod End	Ok
Left Tie Rod End	Ok
Front Right Boots	Ok
Front Left Boots	Ok
Front Right Bushes	Ok
Front Left Bushes	Ok
Front Right Shock	Ok

Rear suspension	No Damage Found
Rear Right Bushes	No Damage Found
Rear Left Bushes	No Damage Found
Rear Right Shock	Average
Rear Left Shock	Average
Steering Wheel	Right hand drive

Odometer Odometer		
Tempering		
Exempt from odometer disclosure Exceeds Mechanical Limits May be Altered Replaced Reading at Time of Renewal Discrepancy Call Title Division	No Problem Found No Problem Found Problem Found No Problem Found No Problem Found No Problem Found No Problem Found	Estimated Current Odometer: 153,038 mi Recent Usage: 22 Km/day Usage Level: Below average 9,700/year (21% more than average of 12,200/year) Recent Fuel Cost: au\$8.95/day at au\$1.7710/litre
Exceeds Mechanical limits Rectified	No Problem Found	
Safety recall check		
no problems found		

www.carexamin.com 4/6



Stolen Vehicle Check	
Police Stolen List: No Records. Beware. Updated one hour ago. Water/Fire Damage: No records	
Statutory Write-off: No records	
Ownership History/ Licence	
2 owners	
Licence Type: Normal	Registration expiry date - 29/04/2025
Plate Type: Standard	Continuous Licence: Yes

Ţ,	,	۱ - ۱	Цa	\at	or
┖	, ,	\c/	пе	:aι	eı
.					

Ac / heater check up	
AC Fitted	Present
AC	Present
Operational	Air Throw
Blower	Present
Cooling	Present
Heating	Present

Electrical & Electronics

Computer Check up	Not present
Master Warning Light	Not Present
Battery Warning Light	Not Present
Oil Pressure Low Warning Light	Not Present
Temperature Warning Light /	Not Present
Gauge	Not Present
Air Bag Warning Light	Not Present
Power Steering Warning Light	Not present
ABS Warning Light	Not present
Key Fob Battery Low Light	Not present

Battery Voltage	12V electrical system
Terminals Condition	Ok
Charging	Ok
Alternator	Ok
Operation	Ok

Gauges	Working

Exterior & Body

www.carexamin.com 5/6



Car frame		
Trunk Lock	Ok	
Front Windshield Condition	Ok	
Rear Windshield Condition	Ok	
Front Right Door Window	Ok	
Front Left Door Window	Ok	
Rear Right Door Window	Ok	
Rear Left Door Window	Ok	
Windscreen Wiper	Cleaning Properly	
Sun Roof Glass	Not Present	

Exterior lights		
Right Headlight (Working)	Working	
Left Headlight (Working)	Working	
Right Headlight (Condition)	Scratches	
Left Headlight (Condition)	Scratches	
Right Taillight (Working)	Working	
Left Taillight (Working)	Working	
Right Taillight (Condition)	Perfect	
Left Taillight (Condition)	Perfect	
Fog Lights (Working)	Present	

Market price analysis

Classified sites price	Auction	s sites price	
\$42,750 below market	\$42,285	below market	
\$44,150 Average dealer fo	precourt price \$43,607	Average Auction fo	recourt price
\$45,982 above market	\$45,155	above market	

👗 Major Title Brand Check	
Calvara laura d	
Salvage brand	No Problem found
Fire brand	No problem found
Hail brand	No problem found
Floord brand	No problem found
Manufacturer buyback	No problem found
Junk or Scrapped brand	problem found
Rebuilt or rebuildable brand	no problem found
Export only vehicle	No problem found

www.carexamin.com 6/6

Goods carrying vehicle

ves

Inspection Result

Pass

Transfer in dispute

No

!Safety Recalls: 4 Records !Sales Records: 2 Records

Warrant of Fitness (WoF):

This is a periodic safety inspection required for light vehicles, typically once a year for vehicles older than twenty two years.

It checks essential vehicle systems such as brakes, tires, lights, steering, suspension, and windshield wipers. It ensures that the vehicle is safe to operate and is not a risk to the driver or others on the road.

If the vehicle passes, a WoF sticker is issued, signifying that the vehicle is "fit" for use.

Certificate of Fitness (CoF):

Certificate of Fitness (CoF): Warrant of Fitness (WoF): As mentioned earlier, this is an inspection for cars that checks essential safety components like brakes, lights, tires, and steering. A valid WoF confirms that a vehicle is fit to be driven on the roads.

Overall Driving Feel:

- • Easy to drive and park, with good maneuverability.
- Reliable engine with smooth performance for everyday use.
- • Comfortable ride quality for a subcompact car.
- • Good fuel efficiency and low maintenance costs.
- Cabin Noise
- Road and wind noise are minimal at lower speeds but become more noticeable at highway speeds, typical for a car in this segment..

It is in good condition

is a reliable, efficient, and comfortable car that's great for city commuting and occasional long drives. It's sporty performer but offers a pleasant and hassle-free driving experience for those seeking practicality and value.

It is good condition, it's a solid choice for a driver